




Mechanical equipment

Overheating conveyor bearing

Overheating motor

Damaged refractory lining

We provide a full detailed report when survey is completed with findings and recommendations



+353 1 8443000



sales@dicksonbearings.ie